

DIE CUT DECAL INSTALLATION INSTRUCTIONS

Step 1 - Clean the area thoroughly!

- Clean the area thoroughly with rubbing alcohol or soap and water. Do not use Windex or similar products because it will leave a residue behind that will prevent the sticker from adhering well.

Step 2 - Prepare the sticker for application

- To prepare the sticker for application firmly rub a squeegee or credit card across the transfer tape. This will remove air bubbles that may have formed and makes the sticker cling to the transfer tape.

Step 3 - Peel off the backing

- Peel the backing off the sticker to expose the adhesive side of the graphic. If the sticker clings to the backing, slowly replace the paper backing and repeat Step 2.

Step 4 - Lower the sticker onto the surface

- Slowly lower the sticker onto the surface adhesive side down and rub it in place firmly with a squeegee or credit card.

Step 5 - Slowly peel the clear transfer tape off

- Slowly peel the clear transfer tape off at an angle (pulling up will lift the graphic). Be careful not to pull the sticker off the surface. If sticker pulls away from the surface repeat Step 4.

For best results:

- Graphics should be applied in shaded, dust free, wind free environment with a temperature range between 70F and 90F.
- Make sure the surface is contaminate and wax free.

*Use a pin to poke any air bubbles in the center and push the air out through the hole.